Site Type	dam (remains)
Site Name	Tarret Burn Dam
Other Name(s)	
Ownership	Sundaysight, Bellingham, Hexham, NE48 2JE
Related Sites	

### LOCATION

National Grid Reference	NY 8088 9164	Km Square	NY 8091		
TAG 2006 Atlas : Map	H2	Air Photo. No	Run AOS/74133 –197		

Modern Parish	Tarset
Historic Parish & Township	Bellingham Tarretburn

### LISTINGS

Scheduled Ancient Monument	Х	Listed	Х
National Monument Record	Х	English Heritage	Х
		Pastscape	
Historic Environment Record	Х	HVA	Х
Grundy	Х	Tarset Books	MM- LX-

## EVIDENCE

Remains extant.

## DESCRIPTION

Remains of a gravity section masonry dam across the Tarret Burn. Said to have been designed by a mining engineer, it failed catastrophically a few weeks after first filling c1897, causing significant damage downstream. A photograph held at Highgreen manor shows the dam with the lake full and spilling over the downstream face. The dam had a maximum height of approx 5-6m above the stream bed and had a very slender section. Preliminary analysis of the stability of the dam indicated it that had a low factor of safety against (a) sliding on the base or (b) overturning.

## TARSET ARCHIVE GROUP SITE RECORD

### IMAGES



NOTES

# REFERENCES



The Tarset Digital Archive by Tarset Archive Group is licensed under a Creative Commons Attribution-NonCommercial-NoDerivatives 4.0 International License.

Please note that Tarset Archive Group members do not guarantee either accuracy or completeness of this record. Data are derived from a variety of sources including its original work; some of these may be copyright. Use of data for any legal purpose should be checked against primary sources. Comments and suggestions to tarsetarchivegroup1@btinternet.com